


NOTES:

1. THE TANGLEWOOD SUBDIVISION HOA SHALL HAVE THE RIGHT AND RESPONSIBILITY TO LOCATE AND MAINTAIN 5' WIDE SIDEWALKS, PER THE SUBDIVISION STREET RIGHT-OF-WAYS, AND IMMEDIATELY ADJACENT TO THE RIGHT-OF-WAY LINE. RECONSTRUCTION OF SIDEWALKS FOR ANY REASON, INCLUDING PUBLIC INFRASTRUCTURE MAINTENANCE OR REPAIR SHALL BE AT THE LIABILITY RELATED TO SAID SIDEWALKS SHALL BECOME THE RESPONSIBILITY OF EACH TANGLEWOOD SUBDIVISION LOT OWNER, FOR SECTIONS OF SIDEWALK IMMEDIATELY ADJACENT TO EACH LOT.

2. THE HOME BUILDER/LOT OWNER, WILL BE RESPONSIBLE FOR THE CONSTRUCTION OF EACH SIDEWALK, ADJACENT AND/OR ON SAID LOT, AT THE TIME THE LOT IS BUILT ON.



TANGLEWOOD

ESTATES ADDITION

EXHIBIT

TBPLS# 10193968 TBPE# F-17299 TBPLS# 10194351 TBPLS# 10194283

SURVEYING & ENGINEERING

1519LLC.com

Waco, TX. 76710 254.776.1519 DALLAS / FT. WORTH 11498 Luna Road, Ste. 203

Farmers Branch, TX. 75234 214.484.8586

J:\MCLENNAN\41000-41999\41900\ENGINEERING\SUBMITTAL\SHEETS\06.15.21 EXHIBITS\41900_SIDEWALK EXHIBIT.DWG LAST SAVED BY: CLAYNE PRINTED BY: CONNOR LAYNE ON 7/1/2021 11:50 AM

SIDEWALK DETAILS

NOT TO SCALE